ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	2	Chowdeshwari Ward
Street ID	**Street Name**	**Significant Landmark**
W0431, W0316, W0310, W0437	NA, Chikkanna Lyt 2nd Crs, Chikkanna Lyt 4th Crs	chowde swhari Layout 6th cross
Segment No.	**Total Length (m)**	
2/C-W0431/S112440	68.69	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	14.91	77.593938	13.107672	77.594075	13.107688	W0431	W0437
2	53.78	77.593805	13.107174	77.593925	13.107660	W0316	W0310

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of RCC Drain chowde swhari Layout 6th cross roads in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	1600000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of RCC Drain chowde swhari Layout 6th cross roads in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	002-16-002013
Work Order No.	**Work Order Date**	**Period of Extention**
EE (YNK D) E-PMT-1/WO/84/2015-16	08/06/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
08/06/2016	07/06/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked / Released (Rs)
T C PRATHAP		0.00
Phone No.	**E-Mail ID**	
9448278838		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		DAYANANDA
Date of Inspection	**Remarks**	
17/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA Ward No: 2 Ward Name: Chowdeshwari Ward Street ID: W0431, W0316, W0310, W0437

Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	17/12/2016	16/01/2017	COMPLETED
SE	VASU K M	17/12/2016	16/01/2017	COMPLETED
EE	VASU K M	17/12/2016	16/01/2017	COMPLETED
AEE	DEVARAJ	17/12/2016	16/01/2017	COMPLETED
AE	DAYANANDA	17/12/2016	16/01/2017	COMPLETED
AE	DAYANANDA	17/12/2016	16/01/2017	COMPLETED

Zone: YELAHANKA Ward No: 2 Ward Name: Chowdeshwari Ward Street ID: W0431, W0316, W0310, W0437